

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

HAER
SD
52-RAC1-V
8-

RAPID VALLEY DITCH
(Murphy Ditch)
Lower Rapid Valley Irrigation Ditches
On the North Side of Rapid Creek
Rapid City Vicinity
Pennington County
South Dakota

HAER No. SD-9

Ron Seirs and Chuck Erickson, photographers, September 1993

- SD-9-1 RAPID VALLEY DITCH (MURPHY DITCH) HEADGATE.
DOWNSTREAM SIDE. VIEW TO NORTHWEST.
- SD-9-2 RAPID VALLEY DITCH (MURPHY DITCH) HEADGATE TRASHRACK.
UPSTREAM SIDE. VIEW TO NORTHEAST.
- SD-9-3 RAPID VALLEY DITCH (MURPHY DITCH) INTAKE CANAL. VIEW TO
NORTHWEST.